

FIG. 1




FIG. 4




FIG. 2




FIG. 5




FIG. 3






FIG. 7

CENTRAL STATION, 202A

200A  
TV SYSTEM, 220A

REMOTE RECEIVING STATION, 206A

FIG. 6




FIG. 8




FIG. 9




FIG. 10




FIG. 19




FIG. 20




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 21




FIG. 22




FIG. 23.




FIG. 24




FIG. 25




FIG. 26




FIG. 27





FIG. 28






FIG. 29








FIG. 31








FIG. 30




FIG. 36

FIG. 40




FIG. 39




FIG. 38





FIG. 37



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**